

Daily Visit Record Report

Your Logo Here

Client:	Industrial Resources Ltd.	Inspection Date:	9/9/2020
Site Location Name:	Sila 21-2	Report Run Date:	11/4/2020 6:40 PM
Client Contact Name:	Jesse Smith	API #:	44-053-01742
Client Contact Phone #:	555-555-5555		
Unique Project ID	20E--Sila 21-2	Project Owner:	Jesse Smith
Project Reference #	20E-02152	Project Manager:	Henry McConnel

Summary of Times

Arrived at Site	9/9/2020 4:40 PM
Departed Site	9/9/2020 7:23 PM

Field Notes

- 17:20** Arrived on site to find a bunch of equipment and other debris scattered around. Workers were on site as well but did not seem to want to talk to us and left shortly after we arrived, although it was nearing 1700 hours.
- 17:22** Pipeline right of way is just to the east of where the access road to the small salt water disposal site is existing and the road has been widened to form a large staging area for the trailers and equipment.

Next Steps & Recommendations

- 1 Talk to landowner about removal of equipment.
- 2 Discuss corrective actions after removal of equipment.

Daily Visit Record Report

Site Photos

Viewing Direction: East



ROW and expanded access road

Viewing Direction: North



Equipment and expanded staging area

Viewing Direction: West



From edge of staging area towards the pad

Viewing Direction: South



Equipment and debris on site

Daily Visit Record Report



Daily Visit Record Signature

Inspector: Kelly Lynburger

Signature: 