

# Daily Visit Record Report

Your Logo Here

Client: Energy Corporation  
Site Location Name: Fed Com #003  
Client Contact Name: Tommy Frederick  
Client Contact Phone #: (555) 555-5555  
Unique Project ID: Fed Com #003  
Project Reference #: 4 Releases from 2006-2019

Inspection Date: 6/18/2020  
Report Run Date: 6/22/2020 7:39 PM  
API #: 55-025-36425  
Project Owner: Henry Jenkins  
Project Manager: Matthew Smith

## Summary of Times

Arrived at Site 6/18/2020 11:07 AM  
Departed Site 6/18/2020 4:22 PM

## Field Notes

**13:49** Discuss remediation depth and area with Tommy. Mostly hand digging because in vicinity of produced water pipeline.  
**13:50** Excavation depth approximately 6".

## Next Steps & Recommendations

- 1 Submit confirmation samples for lab analysis and await results.
- 2 Begin drafting closure report.

## Site Photos

Viewing Direction: West



Remediation in progress

Viewing Direction: South



Remediation in progress

Viewing Direction: East



Remediation in progress

Viewing Direction: East



Final Excavation

Viewing Direction: North



Descriptive Photo - 5  
Viewing Direction: North  
Date: Final Excavation  
Created: 2/12/2020 4:10:10 PM  
Lat: 33.1402, Long: 112.2854

Final Excavation

Viewing Direction: West



Descriptive Photo - 6  
Viewing Direction: West  
Date: Final Excavation  
Created: 2/12/2020 4:10:10 PM  
Lat: 33.1402, Long: 112.2854

Final Excavation

Viewing Direction: Southwest



Descriptive Photo - 7  
Viewing Direction: Southwest  
Date: Final Excavation  
Created: 2/12/2020 4:10:10 PM  
Lat: 33.1402, Long: 112.2854

Final excavation

Viewing Direction: South



Descriptive Photo - 8  
Viewing Direction: South  
Date: Final Excavation  
Created: 2/12/2020 4:10:10 PM  
Lat: 33.1402, Long: 112.2854

Final excavation

Daily Visit Record Signature

**Inspector:** Henry Jenkins

**Signature:** 